EXECUTIVE SUMMARY		i
PURPOSE AND NEED FOR THE F		
	LAN	1
		5 5 7 8 8 11
	l	
CONSULTATION/COORDINATION Public Involvement & Agencies Cons Meeting Summary	N sulted	
APPENDIX 1: MONUMENT PROC		37
		39
APPENDIX 3: INVESTIGATION OF Fort Selden's Extant Remains	THE ADOBE RUINS	43
COLLABORE S EXIAM REMAINS		4 1

The Decay Process	44
Present Preservation Treatments	48
APPENDIX 4: HISTORICAL NARRATIVE	
Fort Selden Military Reservation	49
Fort Selden After the Military	85
Other New Mexico Military Posts	99
Robeldo	104
Ferry	106
Jornado del Muerto	107
Aleman Station	109
San Augustin Pass/Shedd's Ranch	111
Native Americans in the Area During the Fort's Existence	113
Troop Movements	117
Black Troops	119
Leasburg	125
Women	127
APPENDIX 5: ARCHITECTURAL SUMMARY	
Early New Mexico Military Forts	
New Mexico Military Forts, 1870s	
Evolution of Fort Selden	
Second Occupation, 1880-1895	
Early Twentieth Century	153
State Acquisition	
History of Individual Structures and Features	
Cemetery	177
APPENDIX 6: ARCHAEOLOGICAL SUMMARY	179
References Cited	
APPENDIX 7: PERTINENT LAWS. LEGISLATION AND REGULATIONS	193

APPENDIX 8: BIBLIOGRAPHY	195
ADDENDIV O. CLOSSADV	201
APPENDIX 9: GLOSSARY	201

Illustrations

Figure 1.	Project location	1
Figure 2.	Panoramic Photograph of Fort Selden by Steven Kells, 2001	4
Figure 3.	Aerial photograph of Fort Selden State Monument	4
Figure 4.	USGS Map showing Leasburg Dam State Park and Fort Selden State Monument	9
Figure 5.	Photograph of ruins by Steven Kells, 2001	9
Figure 6.	Photographs of Visitor Center by Steven Kells, 2001	10
Figure 7.	Fort Selden State Monument, Aerial Photograph, 1974	16
Figure 8.	Detailed Aerial Photograph of Ruins	23
Figure 9.	This photograph was taken by Gertrude Hill on July 4, 1926, only 35 years after Fort Selden was abandoned	28
Figure A3.1.	Walls of the company quarters	43
Figure A3.2.	Adobe walls of the hospital	43
Figure A3.3.	Fragments of adobe walls that are only inches high and thick	44
Figure A3.4.	Stone foundations of the commanding officer's quarters	44
Figure A3.5.	Photograph of Fort Selden in the 1920s	45
Figure A3.6.	Present typical condition of the adobe walls of the officers' quarters	46
Figure A3.7.	Example of weather-caused deterioration on a west-facing wall surface	46
Figure A3.8.	Example of typical clumping of an adobe wall top	47
Figure A3.9.	Clumping of an end wall that soon will result in loss	47
Figure A4.1.	Map showing fort locations in New Mexico	57
Figure A4.2.	Rio Grande Valley from Santa Fe to El Paso, Texas, 1857	59
Figure A4.3.	Map of the Operational Area of the Army of New Mexico, Civil War, 1862	64
Figure A4.4.	Territory of Fort Selden Reserve	68
Figure A4.5.	Military reservation of Fort Selden, New Mexico	75
Figure A4.6.	Territory of New Mexico, southwest corner	80
Figure A4.7.	"Buffalo Soldier" by Reynaldo "Sony" Rivera	97
Figure A4.8.	Map of the Military Reservation at Ft. Union, New Mexico, 1866	103
Figure A5.1.	Plan of Fort Bayard, New Mexico	138
Figure A5.2.	Plan of Fort Craig, New Mexico	138
Figure A5.3.	Plan of Fort Cummings, New Mexico	139

Figure A5.4.	Plan of Fort McRae, New Mexico	139
Figure A5.5.	Plan of Post near Santa Fe, New Mexico	140
Figure A5.6.	Plan of Fort Selden, New Mexico	140
Figure A5.7.	Plan of Fort Stanton, New Mexico	141
Figure A5.8.	Plan of Fort Union, New Mexico	141
Figure A5.9.	Plan of Fort Wingate, New Mexico	142
Figure A5.10.	Plan of Fort Bliss, Texas	142
Figure A5.11.	Plan of Fort Davis, Texas	143
Figure A5.12.	Military reservation of Fort Selden, New Mexico	145
Figure A5.13.	Plan of Fort Selden, New Mexico, 1871	147
Figure A5.14.	Ground plan, Fort Selden, New Mexico, 1869	148
Figure A5.15.	Elevations of Fort Selden buildings by Rueker, March 29, 1871	149
Figure A5.16.	Fort Selden adobe ruins, photographed March 1955	153
Figure A5.17.	Fort Selden State Monument visitor center	155
Figure A5.18.	"Buffalo Soldier" by Reynaldo "Sony" Rivera	160
Figure A5.19.	Parade ground and flagpole in July 1867	161
Figure A5.20.	Headquarters Building, photographed from the parade ground	162
Figure A5.21.	View of corrals, Headquarters Building, barracs in distance, and Officers' Quarter from northeast	162
Figure A5.22.	The row of officers' quarters at the north end of the parade ground	166
Figure A5.23.	Double house in the row of officers' quarters	166
Figure A5.24.	Double house in the row of officers' quarters	166
Figure A5.25.	The single dwelling at the west side of the row of officers' quarters	166
Figure A5.26.	Fort Selden's barracks, photographed by Nicholas Brown in July 1867	168
Figure A5.27.	Soldiers in front of barracks and hospital to the right	169
Figure A5.28.	This photograph documents the rapid deterioration of the barracks and hospital buildings in the 45 years after the fort was abandoned	169
Figure A5.29.	This interesting photograph, taken from the north by Nicholas Brown in July 1867, shows the corrals at the left	171
Figure A5.30.	The trader's store and Fort Selden Hotel	172
Figure A5.31.	Plan of Fort Selden, 1870	173